

Appendix A

Site Inspection Photographs

Photographs Taken During Site Inspection: October 7, 2009



Photo 1. New recreational trail (Greenway Trail) along Silver Bow Creek near the Rocker OU



Photo 2. New bridge across Silver Bow Creek near Rocker OU. Trail will eventually pass at the toe of the repository.



Photo 3. Silver Bow Creek Greenway trail (looking east)



Photo 4. Monitoring wells with evidence of frost heaving. Town pump visible in background.

Photographs Taken During Site Inspection: October 7, 2009



Photo 5. Damaged fencing along edge of repository. Rip rap visible in foreground.



Photo 6. Damaged gate and well with frost heaving.

Photographs Taken During Site Inspection: October 7, 2009



Photo 7. Empty tanks (used for previous groundwater dosing)



Photo 8. Array of injection wells remaining from groundwater dosing.

Photographs Taken During Site Inspection: October 7, 2009



Photo 9. Tire ruts from repeated driving on repository cap.



Photo 10. Tire ruts on repository cap.