

Appendix A

Site Inspection Photographs

Photographs Taken During Site Inspection: October 6, 2009



Photo 1. Lower Area One Flow Distributor



Photo 2. Lower Area One B1 Cell

Photographs Taken During Site Inspection: October 6, 2009



Photo 3. Lower Area One B1 Cell Sludge Dredging Barge



Photo 4. Lower Area One C1 Cell

Photographs Taken During Site Inspection: October 6, 2009



Photo 5. Sludge Drying Bed at Lower Area One



Photo 6. Little Minah Cap, Active Reclamation of Mountain Con mine dump in the background.

Photographs Taken During Site Inspection: October 6, 2009



Photo 7. Mountain Con headframe and recontoured waste dump with Little Minah dump reclamation in the foreground.

Photographs Taken During Site Inspection: October 6, 2009



Photo 8. Little Minah Dump Reclamation, barren or weedy areas requiring vegetation improvement.



Photo 9. Concrete Cover over the Otisco Shaft

Photographs Taken During Site Inspection: October 6, 2009



Photo 10. Otisco cap showing barren areas and exposed mine waste. Site was reclaimed prior to establishment of soil requirements for vegetative growth.



Photo 11. Looking Northeast over the Otisco shaft cover.



Photo 12. Otisco Shaft cover compromised. (Note that a physical hazard such as a mine shaft is not addressed under CERCLA.)

Photographs Taken During Site Inspection: October 6, 2009



Photo 13. Site inspection tour group at the Minnie Irvine dump (in background).