

Appendix A

Site Inspection Photographs

Photographs Taken During Site Inspection: October 7, 2009



Photo 1. Silver Bow Creek entering the WSP hydraulic control structure and trash racks. Lime silos in background center.



Photo 2. Downstream side of the WSP hydraulic control structure with lime silo towers in background left.

Photographs Taken During Site Inspection: October 7, 2009



Photo 3. Looking upstream along Silver Bow Creek (left side) from the WSP inlet berm. Mill-Willow Bypass is on the right side.



Photo 4. Waste Cap at the WSP upgradient from the Wet Closure Ponds.

Photographs Taken During Site Inspection: October 7, 2009



Photo 5. Meandering Mill-Willow Bypass with healthy vegetation growth along banks.



Photo 6. One of many toe drains along Pond 3 dam adjacent to Mill-Willow Bypass.

Photographs Taken During Site Inspection: October 7, 2009



Photo 7. Riprap repair work to protect against wave run-up along banks of Pond 2.



Photo 8. Pond 2 discharge hydraulic control structure (station SS-5).



Photo 9. Manifolded Toe Drain.



Photo 10. Groundwater interception channel pump house.

Photographs Taken During Site Inspection: October 7, 2009



Photo 11. Scott Brown (EPA RPM) and tour group in the snow.